

THREAD DATA	
THREAD SPEC	1½ - 12 UNF 3A
MAJOR DIA.	
PITCH DIA.	
MINOR DIA.	
WIRE SIZE	
MEASUREMENT OVER WIRES	

2X .06 X 45°

1½ - 12 UNF 3A

R.25

MEDIUM DIAMOND KNURL

.03 X 45°

Ø 1.00 ± .03


3.00

1.50

1.00 ± .06


NOTES:

1) DEBURR ALL EDGES .015 MAX.

UNLESS OTHERWISE SPECIFIED:		NAME	DATE
DIMENSIONS ARE IN INCHES	DRAWN	A. BALOGH	4/2/2019
TOLERANCES:	CHECKED		
1/X or .X ± 1/64 (.0156)	APPROVED		
.XX ± .010	MATERIAL		
.XXX ± .005	CR 1018 STEEL		
X° ± 1°	FINISH	PROJECTION	
ALL SURFACES 			
INTERPRET PER ASME Y14.5-2009			



TITLE:			
PLUG GAGE			
SIZE	DWG. NO.	REV	
A	M220-3	-	
SCALE: 1.5:1	WEIGHT: 1.10	SHEET 1 OF 3	



THREAD DATA	
THREAD SPEC	1½ - 12 UNF 3B
MAJOR DIA.	
PITCH DIA.	
MINOR DIA.	

A

A


NOTES:

1) DEBURR ALL EDGES .015 MAX.

UNLESS OTHERWISE SPECIFIED:		NAME	DATE
DIMENSIONS ARE IN INCHES	DRAWN	A. BALOGH	4/2/2019
TOLERANCES:	CHECKED		
1/X or .X ± 1/64 (.0156)	APPROVED		
.XX ± .010	MATERIAL		
.XXX ± .005	CR 1018 STEEL		
X° ± 1°	FINISH	PROJECTION	
ALL SURFACES 125/	-		
INTERPRET PER ASME Y14.5-2009			



TITLE:			
ROUND NUT			
SIZE	DWG. NO.	REV	
A	M220-3	-	
SCALE: 1.5:1	WEIGHT: 1.85	SHEET 2 OF 3	



THREAD DATA	
THREAD SPEC	1½ - 12 UNF 3B
MAJOR DIA.	
PITCH DIA.	
MINOR DIA.	

A

A

NOTES:
1) DEBURR ALL EDGES .015 MAX.

UNLESS OTHERWISE SPECIFIED: DIMENSIONS ARE IN INCHES TOLERANCES: 1/X or .X ± 1/64 (.0156) .XX ± .010 .XXX ± .005 X° ± 1° ALL SURFACES 125/ INTERPRET PER ASME Y14.5-2009		NAME	DATE
	DRAWN	A. BALOGH	4/2/2019
	CHECKED		
	APPROVED		
	MATERIAL		
	CR 1018 STEEL		
	FINISH	PROJECTION	
	-		



TITLE: ROUND CAP NUT			
SIZE A	DWG. NO. M220-3	REV -	
SCALE: 1.5:1	WEIGHT: 1.98	SHEET 3 OF 3	

Plug Gage General Procedure

- 1) Cut a piece of $\varnothing 1.75''$ mild steel stock to a length of 3.125'' on the bandsaw.**

Tools used: Combination square

- 2) Indicate the stock in a 4-jaw chuck on the lathe to within .001'' total indicator runoff.**

Tools used: 4-jaw chuck, .001''-reading dial indicator, indicator holder with magnetic base

- 3) Face and turn one side to $\varnothing 1.0 \times 1.25''$, leaving sufficient material for the radius.**

Tools used: DCLNR toolholder with CNMG-432 carbide insert, .001''-reading dial indicator with magnetic back, 1-2'' outside micrometer, dial caliper

- 4) Cut and blend the radius.**

Tools used: Indexable carbide radius cutting tool, .001''-reading dial indicator with magnetic back

- 5) Generate the medium diamond knurls.**

Tools used: Clamp-style knurling tool with size 220 knurling rollers, 6'' rule, sharpie, LOTS of cutting oil

- 6) Cut the .030'' $\times 45^\circ$ chamfer.**

Tools used: Chamfering tool, .001''-reading dial indicator with magnetic back

Once you cut the major diameter of the threads, you have passed the point of no return. If you need to break down your setup, this is the last chance to do it.

- 7) Face and turn the other side to major diameter of threads and final overall length.**


Tools used: Collet chuck, 5C collet (best fit to knurled surface), DCLNR toolholder with CNMG-432 carbide insert, .001''-reading dial indicator with magnetic back, 1-2'' outside micrometer, dial caliper

- 8) Cut the .060'' $\times 45^\circ$ chamfers.**

Tools used: Chamfering tool, .001''-reading dial indicator with magnetic back

- 9) Cut the 1 $\frac{1}{2}$ - 12 threads.**

Tools used: Indexable carbide threading tool for coarse threads, center gage, layout dye, thread pitch gage, thread measuring wires (selected according to TPI of threads), 1-2'' outside micrometer, go/no go gage



Round Nut General Procedure

- 1) Cut a piece of $\varnothing 2.5$ " mild steel stock to a length of 2.125" on the bandsaw.**

Tools used: Combination square

- 2) Indicate the stock in a 4-jaw chuck on the lathe to within .001" total indicator runout.**

Tools used: 4-jaw chuck, .001"-reading dial indicator, indicator holder with magnetic base

- 3) Face one side.**

Tools used: DCLNR toolholder with CNMG-432 carbide insert, .001"-reading dial indicator with magnetic back

- 4) Pre-drill through-hole.**

Tools used: Drill chuck, #3 center drill, 5/16" drill, 1 5/16" drill

Once you cut the minor diameter of the threads, you have passed the point of no return. If you need to break down your setup, this is the last chance to do it.

- 5) Bore through-hole to minor diameter of threads.**

Tools used: 1" boring bar with CNMG-432 carbide insert, telescoping gage, 1-2" outside micrometer

- 6) Cut the .060" X 45° chamfer.**

Tools used: 1" boring bar with CNMG-432 carbide insert, .001"-reading dial indicator with magnetic back

- 7) Cut the 1 ½ - 12 threads.**

Tools used: 1" Top Notch-style bar with carbide threading insert for coarse threads, center gage, layout dye, thread pitch gage, go/no go gage

- 8) Flip the part around and indicate it to within .001" total indicator runout.**


Tools used: 4-jaw chuck, .001"-reading dial indicator, indicator holder with magnetic base

- 9) Face the other side to final overall length.**

Tools used: DCLNR toolholder with CNMG-432 carbide insert, .001"-reading dial indicator with magnetic back, dial caliper

- 10) Cut the other .060" X 45° chamfer.**

Tools used: 1" boring bar with CNMG-432 carbide insert, .001"-reading dial indicator with magnetic back



Round Cap Nut General Procedure

- 1) Cut a piece of $\varnothing 2.5$ " mild steel stock to a length of 2.25" on the bandsaw.**

Tools used: Combination square

- 2) Indicate the stock in a 4-jaw chuck on the lathe to within .001" total indicator runoff.**

Tools used: 4-jaw chuck, .001"-reading dial indicator, indicator holder with magnetic base

- 3) Face one side.**

Tools used: DCLNR toolholder with CNMG-432 carbide insert, .001"-reading dial indicator with magnetic back

- 4) Pre-drill blind hole to 1 13/16" depth.**

Tools used: Drill chuck, #3 center drill, 5/16" drill, 1 5/16" drill, 1 5/16" flat bottom drill

Once you cut the minor diameter of the threads, you have passed the point of no return. If you need to break down your setup, this is the last chance to do it.

- 5) Bore blind hole to minor diameter of threads. (Facing bottom of hole with small boring bar is optional.)**

Tools used: 1" boring bar with CNMG-432 carbide insert, .001"-reading dial indicator with magnetic back, telescoping gage, 1-2" outside micrometer

- 6) Cut the groove.**

Tools used: 1" Top Notch-style bar with .189" wide carbide grooving insert, .001"-reading dial indicator with magnetic back, groove micrometer, inside dial caliper

- 7) Cut the inside .060" X 45° chamfer.**

Tools used: 1" Top Notch-style bar with .189" wide carbide grooving insert, .001"-reading dial indicator with magnetic back

- 8) Face to 1.762" depth of blind hole.**

Tools used: DCLNR toolholder with CNMG-432 carbide insert, .001"-reading dial indicator with magnetic back, depth micrometer

- 9) Cut the outside .060" X 45° chamfer.**

Tools used: 1" boring bar with CNMG-432 carbide insert, .001"-reading dial indicator with magnetic back

- 10) Cut the 1 ½ - 12 threads.**


Tools used: 1" Top Notch-style bar with carbide threading insert for coarse threads, center gage, layout dye, thread pitch gage, .001"-reading dial indicator with magnetic back, go/no go gage

- 11) Flip the part around and indicate it to within .001" total indicator runoff.**

Tools used: 4-jaw chuck, .001"-reading dial indicator, indicator holder with magnetic base

- 12) Face the other side to final overall length.**

Tools used: DCLNR toolholder with CNMG-432 carbide insert, .001"-reading dial indicator with magnetic back, dial caliper



PROJECT PLANNING WORKSHEET

OPERATION	TOOLS	CS/RPM
.		

Points Earned	
Total Points Possible	19

PLUG GAGE AND ROUND NUTS INSPECTION REPORT

Student Name

Plug Gage

- 1) Overall Length 3.00 +/- .010
- 2) Thread Length 1.50 +/- .010
- 3) Corner Radius R.25
- 4) Knurl Size, Form: $\varnothing 1.00$ +/- .03, medium diamond
- 5) Knurl Length 1.00 +/- .06

For 1 1/2-12 UNF 3A threads:

- 6) Major Diameter $\varnothing 1.4886 - \varnothing 1.5000$
- 7) Pitch Diameter $\varnothing 1.4411 - \varnothing 1.4459$

Round Nut

- 1) $\varnothing 2.5$ STOCK
- 2) Overall Length 2.00 +/- .010

For 1 1/2-12 UNF 3B thru threads:

- 3) Minor Diameter $\varnothing 1.4100 - \varnothing 1.4198$
- 4) Size, form and pitch verification: Go/No Go Gages

Round Cap Nut

- 1) $\varnothing 2.5$ STOCK
- 2) Overall Length 2.00 +/- .010
- 3) Hole Depth 1.762 +/- .005
- 4) Groove Diameter 1.570 +/- .005
- 5) Groove Width .250 +/- .005

For 1 1/2-12 UNF 3B blind threads:

- 6) Minor Diameter $\varnothing 1.4100 - \varnothing 1.4198$
- 7) Size, form and pitch verification: Go/No Go Gages

Overall appearance (clean, deburred, free of chips)

☐

☐

☐

☐


☐

☐

Table 3. (Continued) Standard Series and Selected Combinations — Unified Screw Threads

Nominal Size, Threads per Inch, and Series Designation ^a	External ^b								Internal ^b					
	Class	Allow- ance	Major Diameter			Pitch Diameter		UNR Minor Dia., ^c Max (Ref.)	Class	Minor Diameter		Pitch Diameter		Major Diameter
			Max ^d	Min	Min ^e	Max ^d	Min			Min	Max	Min	Max	Min
$1\frac{7}{16}$ -28 UN	2A	0.0013	1.4362	1.4297	—	1.4130	1.4088	1.3936	2B	1.399	1.407	1.4143	1.4198	1.4375
	3A	0.0000	1.4375	1.4310	—	1.4143	1.4112	1.3949	3B	1.3990	1.4051	1.4143	1.4184	1.4375
$1\frac{1}{2}$ -6	1A	0.0024	1.4976	1.4703	—	1.3893	1.3772	1.2992	1B	1.320	1.350	1.3917	1.4075	1.5000
	2A	0.0024	1.4976	1.4794	1.4703	1.3893	1.3812	1.2992	2B	1.320	1.350	1.3917	1.4022	1.5000
	3A	0.0000	1.5000	1.4818	—	1.3917	1.3856	1.3016	3B	1.3200	1.3396	1.3917	1.3996	1.5000
$1\frac{1}{2}$ -8 UN	2A	0.0022	1.4978	1.4828	1.4753	1.4166	1.4093	1.3490	2B	1.365	1.390	1.4188	1.4283	1.5000
	3A	0.0000	1.5000	1.4850	—	1.4188	1.4133	1.3512	3B	1.3650	1.3797	1.4188	1.4259	1.5000
$1\frac{1}{2}$ -10 UNS	2A	0.0019	1.4981	1.4852	—	1.4331	1.4267	1.3791	2B	1.392	1.413	1.4350	1.4433	1.5000
$1\frac{1}{2}$ -12 UNF	1A	0.0019	1.4981	1.4809	—	1.4440	1.4344	1.3989	1B	1.410	1.428	1.4459	1.4584	1.5000
	2A	0.0019	1.4981	1.4867	—	1.4440	1.4376	1.3989	2B	1.410	1.428	1.4459	1.4542	1.5000
	3A	0.0000	1.5000	1.4886	—	1.4459	1.4411	1.4008	3B	1.4100	1.4198	1.4459	1.4522	1.5000
$1\frac{1}{2}$ -14 UNS	2A	0.0017	1.4983	1.4880	—	1.4519	1.4464	1.4133	2B	1.423	1.438	1.4536	1.4608	1.5000
$1\frac{1}{2}$ -16 UN	2A	0.0016	1.4984	1.4890	—	1.4578	1.4526	1.4239	2B	1.432	1.446	1.4594	1.4662	1.5000
	3A	0.0000	1.5000	1.4906	—	1.4594	1.4555	1.4255	3B	1.4320	1.4408	1.4594	1.4645	1.5000
$1\frac{1}{2}$ -18 UNEF	2A	0.0015	1.4985	1.4898	—	1.4624	1.4574	1.4324	2B	1.440	1.452	1.4639	1.4704	1.5000
	3A	0.0000	1.5000	1.4913	—	1.4639	1.4602	1.4339	3B	1.4400	1.4480	1.4639	1.4687	1.5000
$1\frac{1}{2}$ -20 UN	2A	0.0014	1.4986	1.4905	—	1.4661	1.4613	1.4391	2B	1.446	1.457	1.4675	1.4737	1.5000
	3A	0.0000	1.5000	1.4919	—	1.4675	1.4639	1.4405	3B	1.4460	1.4537	1.4675	1.4721	1.5000
$1\frac{1}{2}$ -24 UNS	2A	0.0013	1.4987	1.4915	—	1.4716	1.4672	1.4491	2B	1.455	1.465	1.4729	1.4787	1.5000
$1\frac{1}{2}$ -28 UN	2A	0.0013	1.4987	1.4922	—	1.4755	1.4713	1.4561	2B	1.461	1.470	1.4768	1.4823	1.5000
	3A	0.0000	1.5000	1.4935	—	1.4768	1.4737	1.4574	3B	1.4610	1.4676	1.4768	1.4809	1.5000
$1\frac{9}{16}$ -6 UN	2A	0.0024	1.5601	1.5419	—	1.4518	1.4436	1.3617	2B	1.382	1.413	1.4542	1.4648	1.5625
	3A	0.0000	1.5625	1.5443	—	1.4542	1.4481	1.3641	3B	1.3820	1.4021	1.4542	1.4622	1.5625
$1\frac{9}{16}$ -8 UN	2A	0.0022	1.5603	1.5453	—	1.4791	1.4717	1.4115	2B	1.427	1.452	1.4813	1.4909	1.5625
	3A	0.0000	1.5625	1.5475	—	1.4813	1.4758	1.4137	3B	1.4270	1.4422	1.4813	1.4885	1.5625
$1\frac{9}{16}$ -12 UN	2A	0.0018	1.5607	1.5493	—	1.5066	1.5007	1.4615	2B	1.472	1.490	1.5084	1.5160	1.5625
	3A	0.0000	1.5625	1.5511	—	1.5084	1.5040	1.4633	3B	1.4720	1.4823	1.5084	1.5141	1.5625

Three wire method of checking pitch diameter of screw threads



M = Measurement over wires

E = Pitch diameter of thread

D = Basic major or outside diameter

W = Wire Diameter

$M = E + \text{Const.}$

$E = M. - \text{Const.}$

Const. = $3W - .86603P$ (found in chart)

The maximum and minimum pitch diameter (E) for each class of thread can be found in machinery's hand book.

CONVERSION CHART FOR 60° METRIC THREADS

PITCH MM	WIRE SIZE		ADD		CONSTANT	
	MM	INCH	MM	INCH	MM	INCH
0.5	.4572	.018	.6138	.02417	.9386	.03695
0.6	.4572	.018	.4623	.01820	.8520	.03354
0.7	.4572	.018	.3107	.01223	.7654	.03013
0.75	.4572	.018	.2349	.00925	.7221	.02843
0.8	.6096	.024	.6164	.02427	1.1360	.04472
1.0	.6096	.024	.3133	.01233	.9628	.03790
1.25	.7366	.029	.3154	.01242	1.1273	.04438
1.5	1.0160	.040	.7747	.03050	1.7490	.06886
1.75	1.0160	.040	.3958	.01558	1.5324	.06033
2.0	1.1430	.045	.3979	.01567	1.6969	.06681
2.5	1.3970	.055	.4021	.01583	2.0259	.07976
3.0	1.6002	.063	.2540	.01000	2.2025	.08671
3.5	2.0574	.081	.8678	.03416	3.1411	.12367
4.0	2.3368	.092	.9482	.03733	3.5463	.13962
4.5	2.7432	.108	1.4096	.05550	4.3325	.17057
5.0	2.7432	.108	.6519	.02566	3.8995	.15352
5.5	3.0480	.120	.8085	.03183	4.3808	.17247
6.0	3.2258	.127	.5841	.02300	4.1812	.17643

ONE INCH EQUALS 25.400 MILLIMETERS

.03937 INCH EQUALS ONE MILLIMETER

THREAD CHART FOR ALL U.S. 60° THREADS

Select the proper wire size for either the number or threads per inch (US) or thread pitch (metric).

Measured pitch dia (E) equals measurement over wires (M) minus decimal in "CONST" column.

NOTE: Basic P.D. equals basic major diameter plus decimal in "ADD" column minus decimal in "CONST" column.

THREADS PER INCH	WIRE SIZE	ADD	CONST	THREADS PER IN	WIRE SIZE	ADD	CONST
48	.018	.02243	.03596	11 1/2	.055	.03321	.09869
44	.018	.01956	.03432	11	.055	.02722	.08627
40	.018	.01611	.03235	10	.055	.01345	.07840
36	.018	.01190	.02994	9	.063	.02061	.09277
32	.024	.02464	.04494	8	.072	.02656	.10775
28	.024	.01787	.04107	7 1/2	.081	.04093	.12753
27	.024	.01587	.03993	7	.081	.02649	.11928
24	.029	.02385	.05092	6	.092	.02341	.13166
20	.029	.01122	.04370	5 1/2	.108	.04845	.16654
18	.032	.01180	.04789	5	.120	.05689	.18679
16	.040	.02528	.06587	4 1/2	.127	.04421	.18855
14	.040	.01175	.05814	4	.143	.05011	.21249
13	.045	.01842	.06838	3 1/2	.185	.12199	.30756
12	.055	.03870	.09283	3	.185	.04982	.26632

DEAD CENTERS & KNURLS TECHNICAL INFORMATION

CNC Threaded Dead Centers



With 60° Included Angle
For Use On N/C & CNC Live Tailstocks

Features:

- Designed for use in N/C turning centers with live tailstocks • $\pm 0.0005"$ TIR guaranteed
- This center is required where there are no knockout holes
- The point is designed to provide excellent tool clearance

Application:

- Dead center is threaded so nut can be used to remove it from live tailstock in an N/C lathe




Morse Taper	Thread	HSS		Carbide Tipped		Extraction Nuts	
		Order #	Price Ea.	Order #	Price Ea.	Order #	Price Ea.
3MT	1-14	00100735	\$250.80	00100834	\$341.00	99088171	\$61.60
4MT	1 1/4 - 14	00100743	304.70	00100842	410.30	98611478	73.70
5MT	1 3/4 - 12	00100750	434.50	00100859	528.00	90067430	82.50

Jarno, Brown & Sharpe and Straight Shank Specials Available. Contact Nationwide Sales.

Pipe Nose Dead Centers



- Accuracy guaranteed to $\pm 0.0005"$
- Through-hardened to 61-63 Rc
- Riten full service, repair and guarantee apply



Morse Taper	Head Dia. A (In.)	Point Length N (In.)	Clearance E (In.)	Point to Gauge Line K (In.)	Mfr's #	Order #	Price Ea.
2MT	2 1/8	1.831	1/2	2.84	66102	90049552	\$259.33
3MT	2 3/4	2.370	1/2	3.38	66103	05070578	375.41
4MT	2 3/4	2.370	1/2	3.38	66104	99286684	444.57
5MT	3 1/2	3.017	1/2	4.03	66105	99402398	523.59



Basics of...Knurls

A knurling die is used to create a pattern on a cylindrical blank (metal or hard plastic). These dies have V-shaped teeth that deform, displace or push the material rather than cut it. The embossed patterns can be decorative, but more often act as hand grips and are commonly seen on handles, knobs or rollers. Diagonal, diamond and straight are the three most common patterns generated by knurling dies.

Types of Knurls



Straight Tooth



30° Diagonal R.H.



30° Diagonal L.H.



30° Diamond Male



30° Diamond Female

- Straight tooth knurls will produce the straight knurl pattern
- 30° RH diagonal knurls will produce a LH diagonal knurl pattern or a male diamond pattern if used along with a LH diagonal knurl in a double knurl holder
- 30° LH diagonal knurls will produce a RH diagonal knurl pattern or a male diamond pattern if used along with a RH diagonal knurl in a double knurl holder
- 30° male diamond will produce a female diamond knurl pattern
- 30° female diamond will produce a male diamond knurl pattern. This is only recommended if a double knurl holder is unavailable. The knurled blank should be close to the collet and large enough in diameter to prevent deflection

Traversing is not recommended when using diamond knurls (if a longer knurl pattern is required, left and right hand diagonal knurls should be used).

Determining Blank Diameter and the Number of Teeth that will be Rolled

For Circular pitch knurls:

$$\text{Blank Dia.} = (\# \text{ Teeth [part]} / \# \text{ Teeth [die]}) \times (\text{Knurl Dia.} + \text{C.F.}^*)$$

or

$$\# \text{ Teeth [part]} = (\text{Blank Dia.} \times \# \text{ Teeth [die]}) / (\text{Knurl Dia.} + \text{C.F.}^*)$$

TPI *Approximate Value of C.F. (In.)

12-19	0.010
20-29	0.007
30-39	0.005
40-49	0.003
50-80	0.002

*This value is affected by feed rates, blank hardness and diameters of knurl & blank..

For Diametral pitch knurls:

$$\text{Blank Dia.} = \# \text{ Teeth [part]} / \text{D.P. of Knurl}$$

or


$$\# \text{ Teeth [part]} = \text{Blank Dia.} \times \text{D.P. of Knurl}$$

Diametral pitch knurls are designed to permit accurate tracking on standard fractional sized blanks. This makes choosing a blank diameter easier. Due to the Tracking Correction Factor (C.F.), choosing a blank diameter for circular pitch knurling is a bit more difficult and usually involves experimentation.


- C.F. = Tracking Correction Factor. This correction factor takes into account the fact that the tips of the knurl's teeth will penetrate below the blank's diameter by the end of the 1st revolution.

Tips on Choosing the Shape of Knurls


Knurling dies with a full form convex radius on each edge produce the best finishes and increase tool life when axial feeding.



GOOD: Sharp corners on leading edge of tool sees heavy loading, wear rapidly and can break off in extreme conditions.



BETTER: Beveled edge spreads out load, but now the leading edge is a blunt surface requiring higher forces on tool and holder to deform material.



BEST: Convex full form relief gives a "spread out" loading on a sharp leading edge resulting in a smoother precision finish, longer tool life and lower forces on the holder and spindle bearings.

Basic Tips

- Make sure the knurl's axis is parallel to the blank's axis
- Use lots of lubricant
- Never over roll. Try to limit the pattern to only about 90% full
- Increase the feed rate in the 1st revolution. Forming a deeper, wider impression the 1st time around helps to assure that the teeth will track into the initial grooves for all subsequent revolutions